Beveridge Williams

Our Ref: L7077

Office: Melbourne

31 May 2015

S E Murphy

C/- Beveridge Williams Leongatha Office

chisholmg@bevwill.com.au

RE: HISTORICAL AERIAL PHOTOGRAPH REVIEW

CORNER GIBSON STREET AND OLD KORUMBURRA ROAD, LEONGATHA

Dear Gary,

Beveridge Williams Environmental Division has completed a historical aerial photograph review of the above property as requested.

Aerial photographs from 1973, 1979 and 1985 and a review of Parish Plans have been obtained from Spatial Vision CheckSite (refer to attached information). Our findings from the historical review are detailed below.

Stage One Area

Beveridge Williams aerial photograph review indicates that the Stage one area of the site has been used for grazing from at least 1973. No areas of concern were identified on any of the reviewed photographs. Based on Beveridge Williams experience in the assessment of land contamination and our review of the Spatial Vision CheckSite information, we infer that the risk of gross soil contamination is low in Stage one.

Balance of Site

Beveridge Williams aerial photograph review identified areas of potential concern outside of Stage one including the presence of farm sheds and structures, soil disturbance located south the homestead and shed area as well as potential anthropogenic disturbances along the main creek/drain located in the central portion of the site.

Beveridge Williams considers it prudent to complete further investigation of the potential areas of concern noted above. As a minimum the investigation should comprise a detailed site inspection and potentially a soil sampling and testing program.



Beveridge Williams

ACN 006 197 235 ABN 38 006 197 235

surveying urban design town planning civil engineering project management landscape architecture environmental consulting contamination assessment

Melbourne 1 Glenferrie Road (PO Box 61) Malvern Vic 3144 ph: 03 9524 8888

Bairnsdale Shop 7 Riviera Plaza 80-88 Main St (PO Box 1799) Bairnsdale Vic 3875 ph: 03 5152 4708

Ballarat 96 Main Road Ballarat Vic 3350 PO Box 1465 Bakery Hill Vic 3354 ph: 03 5327 2000

Geelong Suite 3 318 Pakington Street Newtown Vic 3220 ph: 03 5222 6563

Leongatha 45A Bair St (PO Box 161) Leongatha Vic 3953 ph: 03 5662 2630

Sale 45 Macalister St Sale Vic 3850 ph: 03 5144 3877

Traralgon 18 Hotham St (PO Box 684) Traralgon Vic 3844 ph: 03 5176 0374

Warragul 60 Queen St Warragul Vic 3820 ph: 03 5623 3072

Wonthaggi 134 Graham St (PO Box 129) Wonthaggi Vic 3995 ph: 03 5672 1505 If you have any queries please do not hesitate to contact me on 03 9524 8812.

 B_{\parallel}

Regards

Andrew Mellett

Manager Environmental Division

Anders Mellett

Attachment: Spatial Vision CheckSite Historical